



Model: R-1002A Bravo / R-1002C Bravo

Kartsana Code: 05-0312-003

Components:

05-0312-003

Repair. File to video: CHANGE OF THE ROLLERBOX

Estimated repair time: 10 minutes

Level of difficulty of the repair:



Tools needed for the repair:

Allen screwdriver N°4

Recommendation:

No special recommendation.